40 W. Broadway St., Shelbyville, IN 46176 Telephone: (317) 392-5119

Fax: (317) 392-5121

EPA Region 5 Records Ctr.

347966

Meridian Automotive 501 Northridge Dr. Shelbyville, In. 46176



40 W. Broadway St., Shelbyville, IN 46176 Telephone: (317) 392-5119

Fax: (317) 392-5121

November 20, 2009

Meridian Automotive 501 Northridge Dr. Shelbyville, In. 46176

To Whom it May Concern:

On November 19, 2009 Deputy Chief Logan, Inspector Robbie Stonebraker of the Shelbyville Fire Department and Bill Myers from the Indiana Department of Environment Management met at the site of Meridian (appx. 1500 hours) and did a walk through of the outside as well as inside of this unsecured building. Mr. Myers took photographs and stated that he would advise his dept. and additional action could occur in the upcoming days. After November 20, 2009, these Items below are follow-up information that has been provided to Shelbyville Fire Department.

On November 20, 2009 Mr. Meyer of IDEM has notified Deputy Chief Tony Logan that he has notified his supervisor and EPA of the issues found.

Deputy Chief Logan today's date has also notified Fire Chief Todd Anderson, Tom Debaun City Planning Director and Mayor Scott Furgeson of the situation at Meridian Automotive.

Inspector Robbie Stonebraker contacted Indiana American Water to confirm that water has been turned off to the entire property, also has contacted Duke Energy to see if they have any intentions of turning electrical power of in the near future. I have also contacted Vectren Gas to confirm that gas has been turned off.

The Shelbyville Fire Department has concerns with the sprinkler system having water in the piping system, when freezing weather arrives we could have further contamination issues. With this problem, water getting into the drains and contaminating our storm sewers. With only two small areas of the building having any diking we could also have contamination on the outside of the building from runoff from the amount of water in this rather large building. With this being said, we feel that if the sprinkler system is not purged we could potentially have a larger cleanup potential, effecting the environment and having a larger impact on the local economy. If the sprinkler system is drained, we as a fire department will then have a dry sprinkler system so in the event of a fire we could better utilize the system in that capacity. Inspector Stonebraker has contacted Koorsen Fire Protection to look at sprinkler system and get a cost estimate to drain system. Koorsen Fire Protection arrived today's date and did a preliminary walk through and will return next week to get more information for pricing to protect system in the building.

40 W. Broadway St., Shelbyville, IN 46176

Telephone: (317) 392-5119

Fax: (317) 392-5121

November 20, 2009 EPA Mark Durno contacted Deputy Chief Logan reference Meridian Automotive Building.

They have assigned Verneta Simon to be the primary (On scene Coordinator) and. Shelly Lam from the Indianapolis location. (See attached info contact sheet)

On November 20, 2009 Inspector Stonebraker received information from Duke Energy that their company will be in contact with our office on Monday concerning the electricity in this building.

Inspector Stonebraker also spoke to Vectren (at the local level) and has been instructed to contact the 1-800-227-1376 number for confirmation that gas has in fact been turned off.

Robbie Stonebraker Fire Inspector

Shelbyville Fire Department

Tony Logan Deputy Chief

Shelbyville Fire Department



40 W. Broadway St., Shelbyville, IN 46176

Telephone: (317) 392-5119

Fax: (317) 392-5121

November 19, 2009

Meridian Automotive 501 Northridge Dr. Shelbyville, In. 46176

To Whom It May Concern:

The company listed above closed for business on or near July 15,2009. I have been checking this facility over the last several months. On November 9,2009 I found several barrels located directly behind the main building in a fenced area and partially covered structure. In this area are appx. 150 drums, some labeled (Hazardous) and some not labeled at all. In one area I found 2 skids of barrels that are double stacked and now are leaning and in danger of falling. I notified Deputy Chief Logan and together we made another inspection of the facility on the outside and found 2 doors unlocked and we entered to find several others barrels and totes located throughout the building. Again some were labeled and some were not. We also found a pit that contained some liquid material

At this time the gas and all water have been turned off to the building. The electricity is still operating and several areas of the building have wires hanging down and are a hazard.

I have been told that when this company closed it has been placed in receivership by an unknown court. Listed below are the contacts that I have been able to locate.

Brad Viegiver

1-248-767-3146

George Miller with Miller, Coffey & Tate LLP

8 Penn Center, Suite 950 1628 John F Kennedy Blvd. Philadelphia, Pa. 19103

215-561-0950

Fax 215-561-0330

Professionally,

Robbie Stonebraker

Fire Inspector

Shelbyville Fire Department

Tony Logari Deputy Chief

Shelbyville Fire Department

Tony Logan

From:

Durno.Mark@epamall.epa.gov [Durno.Mark@epamall.epa.gov]

Sent: Mon 11/23/2009 9:39 AM

To:

Tony Logar

Cc:

Subject:

Meridian Automotive - Shelbyville

Attachments:

Chief Logan,

Thanks for taking the time to discuss the Site with us today. Here is an update for you:

EPA has assigned Verneta Simon to be the primary On-Scene Coordinator (OSC) for this Site. Shelly Lam, our new OSC stationed in Indianapolis, will work with Verneta on this case. Verneta's phone number is 312-886-3601. Shelly's number is 317-417-0980.


The OSCs will coordinate an on-Site meeting date/time with you and IDEM for next week. Our objective will be to establish a strategy for rapid actions to secure the site (move containers indoors, stabilize wastes, secure the building and grounds) and to address any other critical issues that could cause a release of hazardous substances (i.e. draining the water lines to avoid pipe breakage and flooding).

In the mean time, EPA is working on contacting the Site owners/operators to secure proper access and will begin the administrative process to determine potentially responsible parties (PRPs) and cleanup approach. Per the National Contingency Plan and CERCLA, EPA will take responsibility for cleanup activities if no PRPs (i.e. site owners, operators, transporters, disposers of waste) are available or willing to do so, and, if State/Local governments don't have the budget or ability to do so. If EPA conducts the cleanup, we will pursue the PRPs for repayment of our response costs.

Feel free to call me if you have any questions.

Thanks, Mark

Mark Durno
Chief, Emergency Response Section 1
U.S. EPA Region V
Cleveland, Ohio
440-250-1743



Welcome

1

Firm Profile

Our Services

Newsletter

Calculators

Resources

Contact Us



If you have any questions, please feel free to contact us. There are four easy ways to contact us. Simply call, email, fax, or write.

Miller Coffey Tate LLP 8 Penn Center, Suite 950 1628 John F. Kennedy Boulevard Philadelphia, PA, 19103 info@millercoffeytate.com

Phone: 215.561.0950 Fax: 215.561.0330

View Larger Map

Get Driving Directions To Our Office

Please enter your street address and zip code then click on the "Get Directions" button.

Street Address:

ZIP Code:

City:

Optional

State:

Optional

Robbie Stonebraker

From:

Tom DeBaun

Sent: Wed 8/12/2009 3:11 PM

To:

Robble Stonebraker

Cc:

Kevin McLeod; Scott Furgeson

Subject:

Meridian Automotive

Attachments:

I have made contact with Brad Viergiver regarding Meridian. He is to be appointed the person in charge of maintenance and care of this site via the Trustee for the property. **His direct contact number is 248 767-3146**.

I informed him of the order to abate the nuisance, the fact that we'd sent certified mail numerous times and that there were issues on site of major concern. He indicated that he'd let me know something as soon as possible.

If I come up with any additional information I will let you know.



40 W. Broadway St., Shelbyville, IN 46176 Telephone: (317) 392-5119

Fax: (317) 392-5121

November 23, 2009

Meridian Automotive 501 Northridge Dr. Shelbyville, In. 46176

Today, November 23, 2009 Inspector Stonebraker of the Shelbyville Fire Department spoke to Dave Wirrig of Duke Energy about the electricity in the above listed building. At this time they have not made any decisions concerning turning off the electrical. They are current with the bill until Monday November 30 when the next cycle of billing is due.

Robbie Stonebraker

Fire Inspector

Shelbyville Fire Department



40 W. Broadway St., Shelbyville, IN 46176 Telephone: (317) 392-5119

Fax: (317) 392-5121

November 10, 2009

Indiana American Water 1700 McCall Dr. Shelbyville, In. 46176 Wade Amos

Wade,

After reviewing the International Fire Code I have found that in fact you may turn the water off to the Fire Suppression System (Sprinklers) at Meridian Automotive building at 501 Northridge Dr. in Shelbyville Ind. due to the fact that the building is vacant and no heat is on to prevent the freezing of said system. I would request that owners be contacted by letter and informed the system will be shut down and that the internal piping system will possibly still freeze and burst and cause damage to the system and building. I would ask that they drain the internal piping and while the building is vacant we make this a dry system so as in the event of a fire, the Fire Department would still be able to attach to the sprinkler system to aid in the suppression of a fire.

The IFC on vacant buildings is listed in section 311, page 31. If you have any other questions please feel free to contact our office.

Professionally,

Robbie Stonebraker Fire Inspector

Shelbyville Fire Department

Cc. Chief Todd Anderson
Building Commissioner
Tom Debaun



November 12, 2009

Mr. George Miller Miller, Coffey & Tate 8 Penn Center, Suite 950 1628 John F. Kennedy Blvd. Philadelphia, PA 19103

Re: Disconnection of Service-Meridian Automotive-Shelbyville, Indiana

Dear Mr. Miller,

Indiana American Water provides water service to the former Meridian Automotive facility located at 501 Northridge Dr. in Shelbyville, Indiana. Due to non-payment (see attached FINAL BILL), the domestic service has been disconnected (Meter # 070069232A). Unless the amount due is paid, the fire service will be disconnected on November 18th.

Indiana American Water has communicated with the Shelbyville Fire Department on this issue. The Shelbyville Fire Department is aware the fire service may be disconnected. Indiana American Water and the Shelbyville Fire Department both recommend that the internal plumbing within the facility be drained to negate the risk of pipes freezing and bursting inside the building in the event the fire service is disconnected.

Sincerely,

Wade Amos

Operations Superintendent

Indiana American Water-Shelbyville

18 Digit Parcel Number

County Area Section Block Parcel Split TaxID 73 07 30 300 001 000 002

Imported Map Number

041-26040-80

MVPTax Information

Owner Name Meridian Automotive

Address 4635 44th St SE Ste C-100

City State Zip GRAND RAPIDS MI 49512

Property Address

City State Zip

Neighborhood 7302060

Legal Acreage 48.9

Deed Book

Deed Page

Legal Description PT NW PT SW & PT SE 30-13-7 48.90 AC

mypFound Yes

Imported Parcel Number

shape18DigitNumber 73-07-30

SHELBYVILLE FIRE DEPARTMENT



40 W. Broadway Shelbyville, IN 46176 (317) 392-5119 Fax: (317) 392-5121

Deputy Chief Tony Logan tlogan@cityofshelbyvillein.com

SHELBYVILLE FIRE DEPARTMENT



40 W. Broadway Shelbyville, IN 46176 (317) 392-5119 Fax: (317) 392-5121 Cell: 317-401-4703


Robbie J. Stonebraker Fire Inspector rstonebraker@cityofshelbyvillein.com




INDIANA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT Emergency Response Section 24 Hr Spill Line: (888) 233-7745


BILL MYERS On-Scene Coordinator Shadeland Office


TELEPHONE: (317) 308-3037 TOLL FREE: (800) 451-6027 FAX: (317) 308-3063 E-MAIL: wmyers@idem.IN.gov 100 NORTH SENATE AVENUE MC 66-20-2 SHADELAND INDIANAPOLIS, IN 46204-2251 www.ider "gov






with b











 \bigcirc








(

















Duka B



HAZARDOUS WASTE





GRAND RAPIDS. MI KYU 119330 TNHF 119124 US DOT 177267



40 W. Broadway St., Shelbyville, IN 46176 Telephone: (317) 392-5119

Fax: (317) 392-5121

November 23, 2009

Meridian Automotive 501 Northridge Dr. Shelbyville, In. 46176

Today, November 23, 2009 Inspector Stonebraker of the Shelbyville Fire Department spoke to Dave Wirrig of Duke Energy about the electricity in the above listed building. At this time they have not made any decisions concerning turning off the electrical. They are current with the bill until Monday November 30 when the next cycle of billing is due.


Today November 24, 2009 Inspector Stonebraker met with Royce Deckard II of Koorsen Fire & Security to inspect the sprinkler system. He did open all drain valves so no damage will occur in the mild days ahead. He will have quote available by middle of next week to drain sprinkler system. We also shut down the jockey pump and turned the main valve in the pump room (outside) so water would not refill the hydrant and other systems from the outside water source.

inspector Stonebraker met with Amy Skillman the MS4 for the city of Shelbyville and she provided a map with some information about pits located inside the facility and what they hook up to that could contaminate sewer system and to a retention area on the southwest side of the property. (See attached)


Robbie Stonebraker Fire Inspector Shelbyville Fire Department

MERIDIAN AUTOMOTIVE SYSTEMS 501 NORTHRIDGE DRIVE Address SHELBYVI'LLE, IN 46176 317-392-8000 Phone ANDY SCHEELE -> FACURY GIAL **Cross Street Emergency Coordinator** PHONE: 317-392-8124 24 HOUR PHONE: 616-780-2687 ANTONIO VALASCO -> EHS Back-up FEC li PHONE: 317-392-8124 24 HOUR PHONE: 317-512-5041 Extremely HazardousSubstances HYDROCHLORIC ACID BUTOXYETHYL ACETATE, MAK, METHYLENE DIPHENYL, MINERAL **HazardousSubstances** OIL, SODIUM HYDROXIDE, STYRENE, SULFURIC ACID **Emergency Plan Summary Emergency Personnel On-Site** Worst Case Scenario (Zone of Vulnerability) PAINT MIX ROOM, HAZ MAT ROOM, HAZ WASTE STORAGE. POWERHOUSE, ASSEMBLY, SLUDGE PIT, OIL STORAGE ROOM, MOLDING FLOOR, COOLING TOWER Communications **Back-up Communications Notify Employees Employee Training** Storage of Chemicals Hydrant Notes SEE ATTACHED MAP

MERIDIAN AUTOMOTIVE



MERIDIAN AUTOMOTIVE





501 Northridge drive Shelbyville, IN 46176

February 20, 2009

Tom Debaun Shelby County LEPC c/o Shelby County EMA 44 W. Washington Street Shelbyville, IN 46176

Subject:

2008 EPCRA 311 and 312 Reports

Facility Information Sheet

Meridian Automotive Systems, Inc. - SARA ID 341155

Dear Mr. Debaun

Meridian Automotive Systems – Shelbyville Operations is submitting the Emergency Planning and Community Right to know Act information for the 311, Tier II and facility map. Additionally, an updated facility information sheet is included with this submittal.

If you have any questions regarding this information, please contact Mr. Antonio Velasco, EHS Manager at (317) 392-8053.

Sincerely,

Andy Scheele

Plant Manager

Cc: IDEM (Electronic submittal)

Shelbyville Fire Department

Page	1	of	3	pages
	-			

Tier Two EMERGENCY AND HAZARDOUS CHEMICAL INVENTORY Specific Information by Chemical	Facility Identification Name Meridian Autom Street 501 Northridge City Shelbyville SIC Code 3089 FOR OFFICIAL USE ONLY	County Shelby	State IN Zip 46176 d Number	Owner/Operator Name Name Meridian Automotive Phone (313)336-4182 Systems Mail Address 999 Republic Drive Allen Park, Mi 48101 Emergency Contact Name Andy Scheele Title Plant Manager Phone (317)392-8124 24 Hr. Phone (616)780-2687 Name Antonio Velasco Title EHS Manager Phone (317)392-8053 24 Hr. Phone (317)512-5041	-		
Important: Read all instr	ructions before completing j	form Reporting Period	From January 1 to December 31, 20 08	[] Check if information below is identical to the information submitted last year.			
Chemical I	Description	Physical and Health Hazards (check all that apply)	Inventory	Storage Codes and Locations (Non-Confidential) Storage Locations	Optional		
CAS 112072 Chem. Name 2 - Butoxy Check all [] [x] that apply Pure Mix EHS Name	Trade Secret /ethly Acetate [] [X] [] [] Solid Liquid Gas EHS	X) Fire [] Sudden Release of Pressure [] Reactivity [X] Immediate (acute) [x] Delayed (chronic)	Max. Daily Amount (code) 4 Avg. Daily Amount (code) 3 6 5 No. of Days On-site (days)	D 1 4 Paint Mix Room Map 8 D 1 4 Paint Mezzanine Map 14 D 1 4 Haz Mat Room Map 10 D 1 4 Haz Waste Storage Map 11	[]		
CAS 7647010 Chem. Name Hydrochło Check all [] [X] that apply Pure Mix EHS Name	Trade Secret nic acid [] [X] [] [] Solid Liquid Gas EHS	[] Fire [] Sudden Release of Pressure [] Reactivity [x] Immediate (acute) [] Delayed (chronic)	Max. Dally O 4 Amount (code) O 4 Avg. Daily Amount (code) 3 6 5 No. of Days On-site (days)	O 1 4 P{owerhouse Map 1	[]		
Check all [] [X] that apply Pure Mix EHS-Name	Trade Secret amyl Ketone [] [X] [] [] Solld Liquid Gas EHS	[X] Fire [] Sudden Release of Pressure [] Reactivity [X] Immediate (actite) [X] Delayed (chronic)	Max. Daily Amount (code) 4 Avg. Daily Amount (code) 3 6 5 No. of Days On-site (days)	N 1 4 5-gal pails Map 8 Paint Map 8 & 9 D 1 4 Haz Mat Room Map 10 Haz Waste Storage Map 11	[]		
Certification (Read and sign after completing all sections) Certification (Read and sign after complete) Certification (Read and sign after co							

age	2	of	3	gages

	Facility Identification Name Meridian Auto	omotive Systems Inc S	helbyville Operations	Owner/Operator Name Name Meridian Automotive Phone (313)336-4182 Systems
Tier Two	Street 501 Northridg	e Drive		Mail Address 999 Republic Drive
EMERGENCY	City Shelbyville	County Shelby	State IN Zip 46176	Allen Park, Mi 48101
AND				Emergency Contact
HAZARDOUS	SIC Code 3089	Dun & Bra	id Number	
CHEMICAL				Name Andy Scheele Title Plant Manager
INVENTORY		To the state of th		Phone (317)392-8124 24 Hr. Phone (616)780-2687
	FOR	ID#		
Specific	OFFICIAL			Name Antonio Velasco Title EHS Manager
Information	USE	Date Received		Phone (317)392-8053 24 Hr. Phone (317)512-5041
by Chemical	ONLY	7. 4. 19		
Important: Read all in	structions before completing	g form Reporting Period	From January 1 to December 31, 20	08 [] Check if information below is identical to the information submitted last year.
Chemical	Description	Physical and Health Hazards (check all that apply)	Inventory	Storage Codes and Locations (Non-Confidential) Storage Locations
CAS 101688 Chem. Name Methyle Check all [] [X] that apply Pure Mix EHS Name	Trade Secret ne Diphenyl [] [X] [] [] Solid Uquid Gas EHS	[Fire [] Sudden Release of Pressure [] Reactivity [x] Immediate (acute) [x] Delayed (chronic)	Max. Dally 0 4 Amount (code) 0 3 Avg. Daily Amount (code) 3 6 5 No. of Days On-site (days)	D 1 4 Assembly Area Map 2 D 1 4 Sludge Pit Area Map 2 D 1 4 Haz Mat Room Map 10 Haz Waste Storage Map 11
CAS 8012951 Chem. Name Mineral Check all [] [X] that apply Pure Mix EHS Name	[] [X] [] [1	[] Fire [] Sudden Release of Pressure [] Reactivity [Immediate (acute) [X] Delayed (chronic)	Max. Dally 0 4 Amount (code) 0 4 Avg. Dally Amount (code) 3 6 5 No. of Days	C 1 4 Haz Mat Room Map 10 O 1 4 Oil room Map 13 D 1 4 Various areas of the plant
			On-site (days)	
CAS 1310732 Chem. Name Sodium Check all [] [X] that apply Pure Mix EHS Name	Trade Secret Hydroxide [] [X] [] [] Solid Liquid Gas EHS	[Fire [] Sudden Release of Pressure [] Reactivity [X] Immediate (acute) [] Delayed (chronic)	Max. Daily O 4 Amount (code) O 4 Avg. Daily Amount (code) 3 6 5 No. of Days On-site (days)	O 1 4 Powerhouse Map 1 E 1 4 Pretreatment Line Map 5 C 1 5 Pretreatment Line Map 5
on my inquiry of those Indivi Anarew Sche	duals responsible for obtaining the ele owner/operator OR owner/operat	and am familiar with the information information information. I believe that the su	on submitted in pages one through 3 ubmitted information is true, accurate, and comple 2/23/0 Date signs	09 [] I have attached a description of dikes and other

age	3	of	3	pages


) do			nelbyville Operations	Owne Name	System	an Auton	notive	Phone (313)336-4182	2
Tier Two	Street 501 Northridge Driv	/e		Mall A	ddress	999 Rep	ublic Drive		
EMERGENCY	RGENCY City Shelbyville County Shelby State IN Zip 46176								
AND					erk, Mi 4				
HAZARDOUS	SIC Code 3089	Dun & Bra	d Number		acura, do	TILLIOE			
CHEMICAL	0.0 0000			Name Andy Scheele Title Plant Manager					
INVENTORY				Phone		92-8124	24 1	Hr. Phone (616)780-2687	
MATERIORI	FOR	ID#		Phone	(311)3	92-0124	24 F	1r. Phone (010)/00-2007	
Smarific	OFFICIAL	LID#		Name	Antoni	o Velaso		Title FUE Manager	
Specific		Data Baseland		Name				Title EHS Manager	
Information	USE	Date Received		Phone	(317)3	92-8053	24 F	Hr. Phone (317)512-5041	
by Chemical	ONLY				17.16	A. T			
Important: Read all in	structions before completing form	Reporting Period	From January 1 to December 31, 20 08	_ [1]	Check if infor	mation bek	ow is identical to t	the information submitted last year.	
Chemical		Physical and Health Hazards heck all that apply)	Inventory	Container	lype Pressure	Temperature	(No	Codes and Locations n-Confidential) torage Locations	Optional
CAS 100425 Chem. Name Styrene Check all [] [x]		Fire Sudden Release of Pressure Reactivity	Max. Daily 0 5 Amount (code) 0 5 Avg. Daily Amount		C 1 C 1 D 1	4 4 4 4	Molding Ma Cool Room Haz Mat Ro Haz Waste	Map 7	
that apply Pure Mix EHS Name	Solid Liquid Gas EHS [X]	Immediate (acute) Delayed (chronic)	(code) 3 6 5 No. of Days On-site (days)	E					[]
CAS 7664939 Chem. Name Sulfuric	acid	Fire Sudden Release of Pressure	Max. Daily O 3 Amount (code)	E	1	4	Cooling tow	ver Map 12	
Check all [] [X] that apply Pure Mix EHS Name	[] [X] [] [X] [X] Solid Liquid Gas EHS [X	Reactivity Immediate (acute) Delayed (chronic)	0 3 Avg. Daily Amount (code) 3 6 5 No. of Days On-site (days)	E					
CAS Chem. Name	ri —	Fire Sudden Release	Max. Daily Amount (code)	E			-		
Check all [] [] that apply Pure Mix EHS Name	[] [[] [] [] Solid Liquid Gas EHS [If	of Pressure Reactivity mmediate (acute) elayed (chronic)	Avg. Daily Amount (code) No. of Days On-site (days)						[
on my inquiry of those indivi	sign after completing all sections) that I have personally examined and am duals responsible for obtaining the inform celle owner/operator OR owner/operator's e			9		[X] I have	Attachments re attached a sign e attached a list e attached a de uards measure	ite plan t of site coordinate abbreviatio scription of dikes and other	ons



Read Instruction found after this form before completing t	this form	Page of					
Name of facility:		ty ID # Date: (month, day, year)					
Meridian Automotive Systems IND984867267 02-20-2009 Street Address (no P.O. boxes, please): 501 Northridge drive							
City: Shelbyville	County: Six	elby ZIP code: 46176					
Email:Tvelasco O menician autosystems.com		mponents (that require reporting) of mixtures as separate additional copies of this form as needed in order to list all ary.					
Chemical Name	Type of chemical	Physical and Health Hazards					
Hydrochlowic Acid	⊠ EHS	Check all that apply					
	☑ CERCLA	☐ Fire ☐ Sudden Release of ☐ Reactivity.					
CAS# 764 7010	☐ OTHER	Immediate (acute) Delayed (chronic)					
2-Butoxyethly Acetate	☐ EHS	Check all that apply					
	CERCLA	Sudden Release of Reactivity					
CAS# 1/2072	☐ OTHER	Immediate (acute) Delayed (chronic)					
Methyl n-amyl Ketone	☐ EHS	Check all that apply					
	☐ CERCLA	Fire Sudden Release of Reactivity					
CAS# 110430		Immediate (acute) Delayed (chronic)					
Mineral Oil	☐ EHS	Check all that apply					
	☐ CERCLA	☐ Fire ☐ Sudden Release of ☐ Reactivity					
CAS# 8012951		☐ Immediate (acute) ☐ Delayed (chronic)					
	☐ EHS	Check all that apply					
	☐ CERCLA	☐ Fire ☐ Sudden Release of ☐ Reactivity					
CAS#	☐ OTHER	☐ Immediate (acute) ☐ Delayed (chronic)					
	☐ EHS	Check all that apply					
	☐ CERCLA	☐ Fire ☐ Sudden Release of ☐ Reactivity					
CAS#	OTHER	☐ Immediate (acute) ☐ Delayed (chronic)					

FACILITY INFORMATION SHEET

1	Facility ID	Number	IND98486	7267			_	Date	2/20/2009
5	2 Facility Name Meridian Automotive S				Systems, In	c.			
_		Street Address 501 Northridge Drive			-,,		-		
	City	Shelbyville		County	Shelby		 Zip	4617	6
	Email	tvelasco@	meridianau	osystems.	com				
3	3 Is facility subject to SARA Title III			No (Proce	ed to 4)	Yes	If yes, pro	ovide all of the following:	
	Contact N	ame	Antonio Ve	lasco			Phone	317-392-	8053
	Address	501 North				_			and the second second second second second second
*	City	Shelbyville		County	Shelby		Zip	4617	6
	Email	tvelasco@	meridianaul	osystems.	com	Latitude	39.545	8 Longitude	e -85.7908
	Provide th	e name and	business o	f the perso	n filing this f	orm if diffe	rent from co	ntact perso	on.
	Name		- A				Phone		*
						-			
		t best descr		cility.					
	1	Private Inc							
	A	, ,	ricultural (fa						
	L		ernment (mi	unicipal)					
	S	State Gove							
	F	Federal Go	overnment						
	Is this a ne	w name for	the facility?	,	YES	-	N6)	If YES, w	hat was previous name?
	Is this a ne	w owner?			YES		(NO)	If YES, w	hat was previous name?
	Is this a ne	w address?)		YES	(NO	If YES, w	hat was previous name?
	Reason(s) for address change							· /	
4	What is the	e facility's fe	e category,	based on	your current	inventory	(circle one)	>	
	Α		В		С		E		
If the facility is exempt, please provide reason				ns for exem	ption.	Below Th	reshold	Other	
	If other pro	vide additio	nal commer	nts:					



Updated: